



GE INFRASTRUCTURE SENSING RECALLS COMMERCIAL CO2 AND TEMPERATURE SENSORS DUE TO FIRE HAZARD

Release # 10-141

Firm's Recall Hotline: (877) 243-5086

CPSC Recall Hotline: (800) 638-2772

CPSC Media Contact: (301) 504-7908

WASHINGTON, D.C. - The U.S. Consumer Product Safety Commission, in cooperation with the firm named below, today announced a voluntary recall of the following products. Consumers should stop using recalled products immediately unless otherwise instructed.

Name of Product: GE Telaire Airestat and Carrier Single Beam Carbon Dioxide (CO2) and Temperature Sensors

Units: About 9,400 units

Distributor: GE Infrastructure Sensing Inc., of Billerica, Mass.

Hazard: The CO2 and temperature sensors can overheat, posing a fire hazard.

Incidents/Injuries: GE has received three reports in which a cracked capacitor caused the product to overheat and smoke. No injuries have been reported.

Description: This recall involves GE Telaire Airestat CO2 and temperature sensors with model numbers T8010, T8010-C, T8011, T8011-C, T5010, T5010-C, T5011 and T5011-C and Carrier Single Beam CO2 and temperature sensors with model numbers 33ZCT55CO2 and 33ZCT56CO2. The sensors are sold for commercial use and are wall-mounted. The sensors have a Telaire, Carrier, or no logo in front of the unit. The model number is not found on the sensor. Determining if a sensor is included in this recall requires inspection of the internal components of the unit.

Distributed by: Carrier, Automated Components Incorporated (ACI), Devices Inc., Direct Digital Controls, Trane, Alps Control Inc., ATS Control Management Inc. and KMC Controls between November 2000 and March 2005 for between \$150 and \$200. The recalled sensor was distributed for use in commercial buildings.

Manufactured in: USA

Remedy: Building owners should immediately contact GE Infrastructure Sensing for instructions on how to determine if a sensor is included in this recall and if it can be used while awaiting a replacement sensor. Only authorized maintenance personnel should follow these instructions. Building owners with recalled sensors will receive a free replacement sensor.

Consumer Contact: For additional information, contact GE Infrastructure Sensing toll-free at (877) 243-5086 between 8 a.m. and 5:00 p.m. ET or visit the company's website at www.gesensing.com

To see this recall on CPSC's web site, including pictures of the recalled product, please go to:

<http://www.cpsc.gov/cpsc/pub/prerel/prhtml10/10141.html>



NYS Department of State

OFFICE OF
**FIRE PREVENTION
& CONTROL**

phone 518.474.6746

fax 518.474.3240

email fire@dos.state.ny.us