



A. O. SMITH RECALLS WATER PUMP MOTORS DUE TO FIRE HAZARD

Release #08-309

Firm's Recall Hotline: (800) 280-8626

CPSC Recall Hotline: (800) 638-2772

CPSC Media Contact: (301) 504-7908

WASHINGTON, D.C. - The U.S. Consumer Product Safety Commission, in cooperation with the firm named below, today announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately unless otherwise instructed.

Name of Product: Water Pump Motors

Units: About 6,750

Manufacturer: A.O. Smith Electrical Products Co., of Tipp City, Ohio

Hazard: The water pumps with the recalled motors are labeled as containing a one-horsepower motor, but actually contain a 3/4-horsepower motor. Under certain conditions, the smaller motor could overheat, posing a fire hazard to consumers.

Incidents/Injuries: None reported.

Description: The recall involves motors included with lawn sprinkler pumps and jet pumps manufactured by F. E. Myers Co. The recall also includes replacement pump motors that were sold separately.

Model Number	Product Description
QP10	Lawn Sprinkler Pump
QP10B	Lawn Sprinkler Pump with Brass Impeller
HJ100S	Shallow Well Jet Pump
HJ100S-1	Shallow Well Jet Pump with Brass Impeller
HJ100D	Deep Well Jet Pump
HJ100D-LR	Deep Well Jet Pump Less Regulator
HJ100D-1	Deep Well Jet Pump with Brass Impeller
20935A000K	Individually Sold Replacement Motor

Only pumps manufactured between August 2007 and May 2008 are included in the recall. The pump's model number, manufacturing date code and the name "Myers" can be located on the pump's nameplate and packaging. The pump's motor has "A. O. Smith" and model number "C48D52B86" on the motor's nameplate. The replacement motor's packaging has "Myers" and model number "20935A000K" printed on it. Products with an "OK" sticker on the product or packaging are not included in the recall.

Sold at: Plumbing wholesalers and distributors nationwide to independent contractors and plumbers between August 2007 and May 2008. The water pumps sold for between \$500 and \$750 depending on the model, and the replacement motor sold for between \$300 and \$400.

Manufactured in: Mexico

Remedy: Consumers should stop using the recalled units immediately and contact A. O. Smith to arrange for a free replacement of any pumps with affected motors or any affected replacement motors.

Consumer Contact: For further information, contact A. O. Smith at (800) 280-8626 between 8:30 a.m. and 7 p.m. ET Monday through Friday, or visit the firm's Web site at www.regcen.com/pumprecall

To see this recall on CPSC's web site, including pictures of the recalled product, please go to:
<http://www.cpsc.gov/cpsc/pub/prere/phtml08/08309.html>



NYS Department of State

OFFICE OF
**FIRE PREVENTION
& CONTROL**

phone 518.474.6746
fax 518.474.3240
email fire@dos.state.ny.us

WWW.DOS.STATE.NY.US/FIRE