

Safety Alert Bulletin

27 January 2006

Electric Shock Hazard Prompts Recall of Electric Smokers

FOR IMMEDIATE RELEASE

January 26, 2006

Release #06-074

Firm's Recall Hotline: (800) 665-4188

CPSC Recall Hotline: (800) 638-2772

CPSC Media Contact: (301) 504-7908

WASHINGTON, D.C. - The U.S. Consumer Product Safety Commission, in cooperation with the firm named below, today announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately unless otherwise instructed.

Name of Product: Bradley Electric Smokers

Units: About 560

Importer: Bradley Technologies (Canada) Inc., of British Columbia, Canada

Hazard: In addition to the electric cord that plugs into the wall, these units have an electric cord with prongs on both ends that connect the generator to the smoker. If the unit is plugged into the wall socket and one end of the connecting cord is unplugged, there is an electric shock hazard.

Incidents/Injuries: None

Description: The recalled electric smokers include models BTST02 (stainless steel) and BTIS1 (black) and consist of a smoke generator, a smoke tower and two power cords. The model number appears on a silver label on the back of the smoker. The products have a "Bradley Smoker" logo on the door and at the bottom under the red light "Power Indicator."

The recalled black smokers contain one of the following serial numbers:

0508000110000001 to 0508000110000354

0508000113000001 to 0508000113000294

0508000116000001 to 0508000116000354

The recalled stainless steel smokers contain one of the following serial numbers:

0508000111000001 to 0508000111000354.

The serial number appears on a label on the back of each smoker.

Sold by: Retailers nationwide, including Sportsman's Warehouse, Barbeques Galore, Bass Pro, Chez Bubba, from October 2005 through December 2005. The BTIS1 units sold for between \$300 and \$350 and the BTST02 units sold for between \$400 and \$450.

Manufactured in: China

Remedy: Consumers should immediately stop using these smokers and contact Bradley Technologies (Canada) Inc. to determine if the smoker is part of the recall. Bradley Technologies will provide a free replacement smoker to consumers.

Consumer Contact: Call Bradley Technologies (Canada) Inc. at (800) 665-4188 between 8 a.m. and 4:30 p.m. PT Monday through Friday or visit the company's Web site at:

<http://www.bradleysmoker.com>

To view this recall online, please visit our website at:

<https://www.cpsc.gov/cpsc/pub/prerel/prhtml06/06074.html>



New York State Department of State
Office of Fire Prevention and Control
41 State Street
Albany, NY 12231-0001

- phone: (518) 474-6746
- fax: (518) 474-3240
- fire@dos.state.ny.us
- <http://www.dos.state.ny.us/fire/firewww.html>