

Safety Alert Bulletin

21 December 2006

Luxfer SCBA Cylinders May Not Be Properly Tested

On December 14, 2006, Luxfer Gas Cylinders issued an announcement regarding SCBA cylinders, provided to Scott, MSA, Survivair, and Draeger, that may not have been properly tested to meet U.S. Department of Transportation requirements. To learn if your SCBA cylinders are affected read the entire announcement, click on this link:

<http://www.cdc.gov/niosh/npptl/usernotices/>

and scroll to Luxfer Gas Cylinders.

National Personal Protective Technology Laboratory
National Institute for Occupational Safety and Health

NIOSH
PO BOX 18070
626 COCHRANS MILL ROAD
PITTSBURGH PA 15236-0070

Telephone 412-386-4000

Fax 412-386-4051

E-mail:

npptl@cdc.gov

On the Web:

<http://www.cdc.gov/niosh/npptl/>



New York State Department of State
Office of Fire Prevention and Control
41 State Street
Albany, NY 12231-0001

- phone: (518) 474-6746
- fax: (518) 474-3240
- fire@dos.state.ny.us
- <http://www.dos.state.ny.us/fire/firewww.html>