



FIESTA RECALLS TO INSPECT AND REPAIR GAS GRILLS DUE TO FIRE AND BURN HAZARDS

Release #09-020

Firm's Recall Hotline: (866) 740-7849

CPSC Recall Hotline: (800) 638-2772

CPSC Media Contact: (301) 504-7908

WASHINGTON, D.C. - The U.S. Consumer Product Safety Commission, in cooperation with the firm named below, today announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately unless otherwise instructed.

Name of Product: Blue Ember Gas Grills

Units: About 47,000

Importer: Fiesta Gas Grills, of Dickson, Tenn.

Manufacturers: Keesung Manufacturing Co. Ltd. and Unisplendor Corp., of China

Hazard: The gas grills can be assembled improperly exposing the gas burner hoses to excessive heat, posing fire and burn hazards to consumers.

Incidents/Injuries: Fiesta has received 14 reports of grill fires. No injuries have been reported.

Description: The recall involves Blue Ember liquid propane (LP) or natural gas outdoor grills. The recalled model and serial numbers are listed below. The model and serial numbers are printed on a rating plate label on the rear of the grill. The cabinet style grill has two doors and is silver-colored and black or silver-colored and gray. "Blue Ember" is printed on the grill's hood.

Model Numbers	Serial Numbers	
FG50057 or FG50069	08K018821-08K018948	08K006915-08K007042
	08K043658-08K043785	08K044042-08K044297
	08K018309-08K018692	08K048396-08K048523
	08K018693-08K018820	08K007299-08K007426
	08K044554-08K044681	08K044298-08K044425
	08K054921-08K056968	08K018949-08K019332
	08K026501-08K033172	08K016003-08K016258
	08K052233-08K053512	08K017797-08K017924
	08K057481-08K057864	08K044426-08K044553
	08K057765-08K060045	08K048268-08K048395
	08K033317-08K038068	08K017925-08K018052
	08K040117-08K042708	08K042277-08K042634
	08K044572-08K047883	08K015875-08K016002
	08K048790-08K051669	08K053385-08K053640
	08K000001-08K000640	08K007043-08K007298
	08K007425-08K007808	08K038069-08K038196
	08K053641-08K054920	08K051926-08K052052
	08K000641-08K000768	08K060193-08K060320
	08U042773-08U046804	

Sold at: Various home centers and retailers nationwide from November 2007 through June 2008 for about \$450.

Manufactured in: China

Remedy: Consumers should immediately stop using the grills, and inspect the burner hoses to make sure they have been properly assembled. If the hose is to the rear of the installed heat shield, the grill has been improperly assembled and consumers should contact Fiesta for replacement hoses, assembly instructions, and if necessary, for assistance in examining the grill.

Consumer Contact: For additional information, contact Fiesta toll-free at (866) 740-7849 between 7 a.m. and 5 p.m. CT Monday through Friday, visit the firm's Web site at www.fiestagasgrills.com (note: this is a .doc document), or email the firm at mnorman@fiestagasgrills.com

To see this recall on CPSC's web site, including pictures of the recalled products, please go to:

<http://www.cpsc.gov/cpscpub/prerel/prhtml09/09020.html>



NYS Department of State

OFFICE OF
**FIRE PREVENTION
& CONTROL**

phone 518.474.6746
fax 518.474.3240
email fire@dos.state.ny.us

WWW.DOS.STATE.NY.US/FIRE