



HYUNDAI-KIA RECALL: POSSIBLE ELECTRICAL SYSTEM FIRE POTENTIAL

Vehicle Make / Model:

KIA / SORENTO
KIA MOTOR / SOUL

Model Year(s):

2011
2010

NHTSA CAMPAIGN ID Number:

10V388000

Summary:

HYUNDAI-KIA IS RECALLING CERTAIN MODEL YEAR 2010 SOUL AND MODEL YEAR 2011 SORENTO VEHICLES MANUFACTURED FROM SEPTEMBER 7, 2009 THROUGH JULY 30, 2010. A LIMITED NUMBER OF WIRING HARNESSSES SUPPLIED BY JCI AND USED FOR THE LIGHTING IN THE KIA SOUL VEHICLE'S ADVANCED LIGHTING SPEAKERS, LOCATED IN THE FRONT DOOR TRIM PANELS, AND THE KIA SORENTO VEHICLE'S INTERIOR ACCENT ILLUMINATION, LOCATED IN THE FRONT AND REAR DOOR TRIM PANELS, MAY HAVE BEEN IMPROPERLY SOLDERED.

Consequence:

WHEN THE LIGHTS ARE ILLUMINATED UNDER CERTAIN CONDITIONS, AN ELECTRICAL SHORT MAY OCCUR THAT CAN RESULT IN A FIRE.

Remedy:

DEALERS WILL REPLACE THE WIRING HARNESSSES FOR THE LIGHTS IN THE KIA SOUL VEHICLE'S ADVANCED LIGHTING SPEAKERS, AND THE WIRING HARNESS FOR THE KIA SORENTO VEHICLE'S INTERIOR ACCENT ILLUMINATION. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN DURING SEPTEMBER 2010. OWNERS MAY CONTACT KIA CONSUMER ASSISTANCE CENTER AT 1-800-333-4542.

Notes:

KIA'S SAFETY RECALL CAMPAIGN NUMBER IS SC083. OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).



Distributed by the
NYS Division of Homeland Security and Emergency Services

OFFICE OF
**FIRE PREVENTION
& CONTROL**

phone 518.474.6746
fax 518.474.3240
email fire@dos.state.ny.us